## National Transportation Sufety Board FACTUAL REPORT AYIATION

NTSB ID: DEN03LA005 Aircraft Registration Number: N7672K

Occurrence Date: 10/09/2002 Most Critical Injury: None

Occurrence Type: Accident Investigated By: NTSB

Location/Time

Nearest City/Place	State	Zip Code	Local Time	Time Zone	
Watkins	СО	80137	1300	MDT	
Airport Proximity: On Airport	Distance Fror	n Landing Facility:		Direction Fro	m Airport:

Aircraft Information Summary

All clait illioithation Suninary										
Aircraft Manufacturer	Model/Series	Type of Aircraft								
Piper	PA-20	Airplane								

Sightseeing Flight: No Air Medical Transport Flight: No

## Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On October 9, 2002, at 1300 mountain daylight time, a Piper PA-20, N7672K, was substantially damaged during a ground loop while landing at Front Range Airport, Watkins, Colorado. The commercial pilot and his passenger were not injured. The pilot was operating the airplane under Title 14 CFR Part 91. Visual meteorological conditions prevailed for the personal cross-country flight that originated from Sylvia, Kansas, approximately 2 hours 30 minutes before the accident. No flight plan had been filed.

The assistant airport manager said the airplane was landing on runway 8. He said the airplane ground looped and exited the south side of the runway.

According to his accident report, the pilot said the left brake was "not there" on landing roll, and the right brake grabbed. He said a leakage of the left brake line was discovered upon examination of the airplane which resulted in the failure of the left brake.

The outboard 8 feet of the left wing was bent upward, and the tip of the left elevator was bent.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN03LA005

Occurrence Date: 10/09/2002

THE TOTAL AND A PROPERTY OF THE PROPERTY OF TH			10,00,2002										
AVIATION		Occui	rrence Ty	ype: A	ccident								
Landing Facility/Approach Infor	mation												
Airport Name			Airport IE	D: A	Airport Eleva	ion	Run	way Used	Runwa	ay Lengt	:h	Runv	way Width
FRONT RANGE			FTG	TG 5512 Ft. MSL 08 8000				8000			100		
Runway Surface Type: Asphalt													
Runway Surface Condition: Dry													
Type Instrument Approach: NONE													
VFR Approach/Landing: Unknown													
Aircraft Information													
Aircraft Manufacturer Piper				odel/Se A-20	eries					Serial 20-49	Numbe 93	er	
Airworthiness Certificate(s): Normal													
Landing Gear Type: Tailwheel													
Homebuilt Aircraft? No N	umber of Seats:	4	Cert	Certified Max Gross Wt.				2000 LBS Number			er of Engines: 1		÷ 1
Engine Type: Reciprocating	Engine Manufacturer: Model/Series: Lycoming O-360 A4A						Rated Power: 180 HP						
- Aircraft Inspection Information													
Type of Last Inspection			Date of Last Inspection			Time Si	Airframe Total Time						
Annual			06/2002					30 Hours 4041 Hour				1041 Hours	
- Emergency Locator Transmitter (EL	Γ) Information												
ELT Installed? Yes	ELT Operate	ed? No				ELT	Aided i	n Locating Ac	cident S	ite? No	)		
Owner/Operator Information													
Registered Aircraft Owner			Stre	eet Add	lress P.O. Box	157							
Robert K. Vasey			City							Stat KS	e	Zip Code 67581	
			Street Address										07301
Operator of Aircraft			Same as Reg'd Aircraft Owner										
Same as Reg'd Aircraft Owner			City							Stat	e	Zip Code	
Operator Does Business As:							O	perator Desig	nator Co	ode:			
- Type of U.S. Certificate(s) Held: No	пе												
Air Carrier Operating Certificate(s):													
Operating Certificate:					Operator C	ertific	cate:						
Regulation Flight Conducted Under: F	art 91: Genera	al Aviati	ion										
Type of Flight Operation Conducted: I	ersonal												
		FACTU	JAL RE	EPORT	Γ - AVIATI	ON							Page 2

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN03LA005

Occurrence Date: 10/09/2002

AVIATION Occurrence Type: A					cident									
First Pilot Information														
Name					City					tate	Date	of Birth	Age	
On File					On File	n File On File On File 70							70	
Sex: M Seat Occupied:	Left	Prir	ncipal Profes	sion: Unkno	own	Certificate Number: On File								
Certificate(s): Commercial														
Airplane Rating(s): Multi-engine Land; Single-engine Sea														
Rotorcraft/Glider/LTA:														
Instrument Rating(s): Airplane														
Instructor Rating(s): None														
Type Rating/Endorsement for Accident/Incident Aircraft? No Current Biennial Flight Review? 11/2001														
Medical Cert.: Class 2	aivers/lim	۱.		Date of	Last N	Medical I	Exam	: 04/2002						
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night		Instrument Actual Si		ed	Rotorcraft		Glider	Lighter Than Air	
Total Time	8560	2520	8490	65	4	65	5	3	40		1	3		
Pilot In Command(PIC)	8350	2520		59	4	65	5	3			$\perp$			
Instructor						$\dashv$					$\dashv$			
Last 90 Days	39	30	39	3				9			$\dashv$			
Last 30 Days  Last 24 Hours	20 2	20	20		1	1					$\dashv$			
Seatbelt Used? Yes						ovico	logy Perfo	rmod2 N		I	Socon	d Pilot?		
Seather Oseu? Tes	51100	lder Harness	Usea? NO		110	JAICO	nogy Feno	illeu: M	<u> </u>		becom	u Filot:		
Flight Plan/Itinerary														
Type of Flight Plan Filed: No	one													
Departure Point					5	State	Air	port Ident	ifier	er Departure Time			Time Zone	
STAFFORD					K	S	3Т	·A		1030			MDT	
Destination					5	State Airport Identifi			ifier					
Watkins		CO FTG												
Type of Clearance: Unkno	wn													
Type of Airspace: Class I	E													
Weather Information														
Source of Briefing: Unkno	wn													
Method of Briefing: Unkno	wn													
			FACTUAL	REPORT	- AVIAT	TON	1						Page 3	

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN03LA005

Occurrence Date: 10/09/2002

Occurrence Type: Accident

	ETYBOR		Occurrenc	e Type:	Acciden	τ									
Weather	Information														
WOF ID	Observation Time	Time Zone	WOF Elevati	on	WOF Di	stance Fro	om Accid	dent Site		Direction From Accident Site					
DEN	1453	MDT	5431 Ft.	. MSL					295 Deg. Mag.						
Sky/Lowes	st Cloud Condition: Few					7500 Ft. A	\GL	Condition of Light: Day							
Lowest Ce	illing: None		Ft.	AGL	Visibi	lity:	10	SM	Altiı	meter:	30.00	"Hg			
Temperatu	ıre: 23 °C [	Dew Point:	-4 °C	Wind	Direction:	Variable		Density Altitude: 7683							
Wind Spee	ed: 4	Gusts:		Weath	ner Condti	ons at Acc	cident S	Site: Visual C	Condi	itions					
Visibility (F	RVR): Ft.	Visibility (RV	/V)	SM	Intensity	of Precip	itation:								
Restriction	s to Visibility: None														
Type of Precipitation: None															
Accident	Information														
Aircraft Da	mage: Substantial		Aircraft Fire	e: None	one Aircraft Ex					Explosion None					
Classificati	on: U.S. Registered/U.	.S. Soil													
- Injury Su	mmary Matrix	Fatal Seri	rious Mino	or	None	TOTAL									
First Pi	lot				1		1								
Second	d Pilot						7								
Studen	t Pilot						┑								
Flight I	nstructor						┑								
Check	Pilot						┑								
Flight E	Engineer						7								
Cabin A	Attendants						7								
Other C	Crew						7								
Passen	ngers				1		1								
- TOTAL A	ABOARD -				2		2								
Other 0	Ground Ground						7								
- GRANE	O TOTAL -				2		2								

National Transportation Safety Board

## FACTUAL REPORT AVIATION

NTSB ID: DEN03LA005

Occurrence Date: 10/09/2002

Occurrence Type: Accident

Λ _		::	-4-	-4:.		1	<u>.                                    </u>		1	: -	
Αc	ırn	m	SIL	ลบ	ve	ım	()	m	เลเ	I()	m

Investigator-In-Charge (IIC)

James F. Struhsaker

Additional Persons Participating in This Accident/Incident Investigation:

John D Stevenson Denver Flight Standards District Office Denver, CO 80249